

SAPC - 18526
Copy 2 of 3

16 August 1957

Dear Jim:

Attached is information on the speed correction equipment for magnetic tapes.

The estimated cost is \$2005 per A, B₁, B₂ system. Later discussions indicated that the parts might run as high as \$2500 per set.

If Russ wants any will order them for you.

Dan

25X1A PCS/DCI: [REDACTED]:pf (8/16/57)

Distribution:

25X1A Orig: - [REDACTED]

25X1A ✓ 2 - [REDACTED] A-101 - see *carves* *SAPC-18394 for (encl)*
3 - Proj. Chrono (RI)

DOCUMENT NO. _____
NO CHANGE IN CLASS. *X*
☐ *2012*
DATE: *11/1/82* REVIEWER: 004540